



Hydraulic Fabric Burst Tester According to ISO 13938-1

Description

- Test area 50 cm² (other are as option)
- Hydraulic pressure increase control
- Elastic diaphragm
- Thermal printer
- Touch display showing pressure and height of sample at burst
- USB data output to MS Excel
- Manual valve for flow adjustment of hydraulic system
- Pneumatic grip of sample
- Height indication of sample at bursting using linear transducer
- Pressure indication of sample piece
- Maximum pressure is 1000KPa (other pressures available on customer request)
- Clamping pressure adjustment of sample piece
- Burst pressure indication
- Displacement measurement
- Burst displacement indication using liner transducer
- Training video included